





A	B C	D	
			7
2			11G.3
3		•	
4 4			

















Fig. 6











	I																									
600	ဉ်					[1] = type[1]	1	[1] = data[1]																		
38	Ψ,					0] = type[0]	[0] = description[0]	0] = data[0]																		
340, 850,	E					ኁ] ^ [E]	^																		
689	O				[0] = Worksheet1 name	[1] ~								[0] = Worksheet2 name	Σ								[0] = Worksheet3 name	?		
078	ပ				^ 0									? E									(2)			
	В			= Workbook	11 -																					
gos 7	A			\$ 101 ×	~	+	.,	~	7	3	6	. 0	1	2	3	4	2	9	7	8	6	o.	Τ.	2	33	4:

Fig. 12

Content Area 8 Action Items Nylon impeller has been observed to disintegrate in strong H2S04 solution, shedding particles on wafers exposed to resist strip. The proposed change is intended to solve this Project Set Up Functional Group Wet Chemistry Impacts all Type 6 wet clean stations in all factories running the S3003 process. Electrical Application Tabs Schedule Change Impeller H2So4 pump to Teflon Current Status: Approved by Factory Executive Team Pre-implementation 2 unread emails (J.Hyde, D. Zook) 202 Public Meeting Minutes Yield Data View List SPC H202 Filter Recycling 3 pending action items Global High Risk Equipment Mod View External List Whiteboard Check Lists Origination Date: 05-JUNE-2000 Experiment Long Text Description: Global Operation Functions Add to List Originator: Jack Hyde Forum Based on Project Project Attributes: WorkFlow Type Impact Level Specifications Email Sharing Coauthors: Sponsors Summary Meet Online Search database | Program Setup | Vinestone Home| 06022000-122 Increase Beam Curment in Tip Implant 06082000-127 Change Impeller H2So4 pump to T-05242000-127 Retarget Oxide Thickness in Furnace search projects +Electrical Systems Coordination Team +Factory Layout Coordination Team +Water Systems Coordination Team New -Front End Process Review Team Back End Process Review Team VS-WorkWeb View by Review Group +Facilities Management Team +Interlayer Isolation Team +Safety Coordination Team **Executive Program Committee** Fig. 13 -Factory Executive Team Process Executive Team +Interconnect Team -Transistor Team +Isolation Team +Bipolar Team View Tree

Communication Tools